

W0963	1845 Norman Dr	Fair	8'' PVC Pipe	Location is 1ft from the sidewalk and is in front of heribert fitness. It has an 8''pvc pipe coming out, 8''pvc coming in also a 4''pvc coming in as well. The manhole ring and cover is good the lid is 23 ½'' It has a little odor to it. Its 9ft deep and the flow is heavy and heading southwest. The steps look fine also manhole is precast do not see any problems at this time.
W0965	1845 Norman Dr	Fair	8''PVC Pipe	Manhole is the straight lane asphalt manhole ring and cover is good. It has 8''pvc pipe coming in and 8''pvc pipe out it is precast. 10ft deep flow is light there no problem here. The steps looks good, it has a little odor but not much. The flow is going south, the lid is 23''.
W3370	1801 Iola Dr	Poor	8''	Brick manhole 7ft deep with 8'' main flowing in from the east. Ring and cover in good condition located in the middle of the intersection of E. Alden and Iola 24'' lid. Getting some infiltration in the bricks.
M0278	301 S Blanchard St	Poor	15''	Manhole is precast, 12ft deep flowing from north to east. 24'' lid. Infiltration into the manhole. Ring is deteriorating from gas and needs to be replaced. Located in the parking lot in the front.
M1561	813 S Lee St	Fair	8''	Manhole was brick, 8ft deep with 8'' main flowing north. 24'' lid. Ring and cover in good condition. Located in the middle of the road.
W0962	1839 Norman Dr	Fair	8''PVC pipe	Manhole is located in driveway asphalt, lid is 23''. It was 8''pvc pipe coming in a 8''pvc out of main. Also has a 6''pvc pipe coming into main the flow is heavy and direction is going west. 7 ½ ft deep and precast there seems to be no problems, no odor at this manhole ring and cover is good.
W0964	1840 Norman Dr	Fair	8''PVC Pipe	Manhole has 2-8'' in and out precast. The flow is heavy and direction is south. There is no odor manhole ring and cover is good. Manhole is located in turning lane asphalt. Pipe is pvc inside main. Lid is 23''