

	<p>1.b. The measurable goal must be specified for each BMP. Each BMP must be executed at least annually.</p> <p>1.c. Details on the implementation of each BMP, including documentation of activities performed during the reporting period, must be provided in each annual report.</p>
--	--

For new permittees, the program shall, at a minimum, implement the requirements shown in Table 4.2.2(b) below and include descriptions of how they are implemented in the SWMP:

Table 4.2.2(b) Public Involvement/Participation - Best Management Practices (New Permittees)

BMPs	Measurable Goals
1. Public Involvement/Participation Program	<p>1.a. Develop a public involvement/participation program. Describe the program in the SWMP and submit the program to EPD for review and approval in accordance with Part 3.2.2 of this permit. The Public Involvement/Participation Program must include the minimum number of BMPs detailed in Part 4.2.2 and include BMPs chosen from the list in Table 4.2.2(a), BMP 1.a. or other BMPs approved by EPD.</p> <p>1.b. Implement the public involvement/participation program in accordance with the implementation schedule specified for each BMP in the SWMP. The measurable goal must be specified for each BMP. Each BMP must be executed at least annually.</p> <p>1.c. Details on the implementation of each BMP, including the status of implementation and documentation of any activities performed during the reporting period, must be provided in each annual report.</p>

4.2.3 Illicit Discharge Detection and Elimination (IDDE)

The permittee must develop, implement and enforce a program to detect and eliminate illicit discharges (as defined in 40 CFR Part 122.26(b)(2)) into its MS4. The permittee must:

- 4.2.3.1 Develop, if not already completed, a storm sewer system map, showing the location of all outfalls and the names and location of all waters of the State that receive discharges from those outfalls;