

Project Details

Client: SOUTHLAND COMPLIANCE SERVICES

Project Name: ALAPAHA TREATMENT POND

Shipping and Receiving

Date/Time Received: 3/3/2021 2:15:00 PM If present, were cooler custody seals intact?

Sampling Personnel: HARLOW Yes No N/A

Shipping Method: Laboratory Courier If present, were sample bottle custody seals intact

Shipping Tracking Number: Yes No N/A

Thermal Preservation

Cooler Temp Method: Sample Temperature Were cooler temperatures in compliance? (0.1-6.0C)

Thermometer ID: 16032413 Yes No N/A

Number of Coolers: 1 Cooler Temperatures: 4.9

Chain of Custody

Was the chain-of-custody received in coolers? Yes No N/A

Was the chain-of-custody signed and properly relinquished? Yes No N/A

Does the chain-of-custody agree with samples and analyses? Yes No N/A

Container Receipt

Were samples received in appropriate bottleware for analyses? Yes No N/A

Was sufficient volume submitted for analyses requested? Yes No N/A

Were samples received within method holding times? Yes No N/A

Were VOA vials received with zero headspace? Yes No N/A

Were aqueous samples received at an acceptable pH? Yes No N/A

pH Test Strip Manufacturer / Lot #: MQUANT-HC989495

Comments

I certify I have answered the questions contained herein to the best of my knowledge and have affixed labels with unique IDs onto each sample container received. I certify any discrepancies regarding the samples as received by the laboratory have been documented completely in the comments section of this form.

BCR

Brandon Ray