

**WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region**

Project/Site: Adirondack Tract City/County: Charlton County Sampling Date: 03/22/2019  
 Applicant/Owner: Twin Pines Minerals, LLC State: GA Sampling Point: UDP-1  
 Investigator(s): C. Terrell / C. Stanford (TTL) Section, Township, Range: Not Available  
 Landform (hillslope, terrace, etc.): Flatwoods Local relief (concave, convex, none): None Slope (%): 0-2%  
 Subregion (LRR or MLRA): LRR T / MLRA 153A Lat: 30.5191001892089 Long: -82.0980987548828 Datum: NAD83  
 Soil Map Unit Name: Leon fine sand, 0 to 2 percent slopes NWI classification: none

Are climatic / hydrologic conditions on the site typical for this time of year? Yes \_\_\_\_\_ No  (If no, explain in Remarks.)  
 Are Vegetation Yes, Soil Yes, or Hydrology Yes significantly disturbed? Are "Normal Circumstances" present? Yes  No \_\_\_\_\_  
 Are Vegetation No, Soil No, or Hydrology No naturally problematic? (If needed, explain any answers in Remarks.)

**SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc.**

Hydrophytic Vegetation Present? Yes <input checked="" type="checkbox"/> No _____ Hydric Soil Present? Yes _____ No <input checked="" type="checkbox"/> Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>	Is the Sampled Area within a Wetland? Yes _____ No <input checked="" type="checkbox"/>
Remarks: - Vegetation historically impacted by silvicultural activities (planted pine). - Soils/Hydrology historically impacted by silvicultural activities (bedding for planted pine). - Drier than normal, but not drought conditions.	

**HYDROLOGY**

<b>Wetland Hydrology Indicators:</b> <u>Primary Indicators (minimum of one is required; check all that apply)</u> ___ Surface Water (A1)      ___ Aquatic Fauna (B13) ___ High Water Table (A2)      ___ Marl Deposits (B15) <b>(LRR U)</b> ___ Saturation (A3)      ___ Hydrogen Sulfide Odor (C1) ___ Water Marks (B1)      ___ Oxidized Rhizospheres along Living Roots (C3) ___ Sediment Deposits (B2)      ___ Presence of Reduced Iron (C4) ___ Drift Deposits (B3)      ___ Recent Iron Reduction in Tilled Soils (C6) ___ Algal Mat or Crust (B4)      ___ Thin Muck Surface (C7) ___ Iron Deposits (B5)      ___ Other (Explain in Remarks) ___ Inundation Visible on Aerial Imagery (B7) ___ Water-Stained Leaves (B9)	<u>Secondary Indicators (minimum of two required)</u> ___ Surface Soil Cracks (B6) ___ Sparsely Vegetated Concave Surface (B8) ___ Drainage Patterns (B10) ___ Moss Trim Lines (B16) ___ Dry-Season Water Table (C2) ___ Crayfish Burrows (C8) ___ Saturation Visible on Aerial Imagery (C9) ___ Geomorphic Position (D2) ___ Shallow Aquitard (D3) ___ FAC-Neutral Test (D5) ___ Sphagnum moss (D8) (LRR T,U)
<b>Field Observations:</b> Surface Water Present? Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____ Water Table Present? Yes <input checked="" type="checkbox"/> No _____ Depth (inches): <u>20</u> Saturation Present? (includes capillary fringe) Yes _____ No <input checked="" type="checkbox"/> Depth (inches): _____	Wetland Hydrology Present? Yes _____ No <input checked="" type="checkbox"/>
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	
Remarks: FAC-Neutral Test Results: <b>Negative</b> FACW and OBL: <b>1</b> to      FACU and UPL: <b>2</b>	