



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

Lovell Engineering Associates
3998 Inner Perimeter Road
Valdosta, GA 31602

PO #: n/a
Client Project #: Lowndes County Impaired
Date Sampled: Apr 7, 2020
Apr 9, 2020; Invoice: 433390

Report Summary

Date Received: Apr 7, 2020

FCL Project Manager: William J. Rogers

Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
433390SW1	Staten Rd.	COLILERT-18 EPA245.1	AML AJE	North Lab Main Lab	Surface Water
433390SW2	Hwy 122 E	COLILERT-18 EPA245.1	AML AJE	North Lab Main Lab	Surface Water
433390SW3	Hahira WWTP	COLILERT-18	AML	North Lab	Surface Water
433390SW4	Union Rd	COLILERT-18	AML	North Lab	Surface Water
433390SW5	Old Valdosta Rd.	COLILERT-18	AML	North Lab	Surface Water
433390SW6	Shiloh Rd	COLILERT-18	AML	North Lab	Surface Water
433390SW7	N. Valdosta Rd.	COLILERT-18 EPA245.1	AML AJE	North Lab Main Lab	Surface Water
433390SW8	Weatherington Ln	COLILERT-18 EPA200.8 EPA245.1	AML EVB AJE	North Lab Main Lab Main Lab	Surface Water
433390SW9	Hwy 84	COLILERT-18 EPA200.8 EPA245.1	AML EVB AJE	North Lab Main Lab Main Lab	Surface Water
433390SW10	Ousley Rd	COLILERT-18	AML	North Lab	Surface Water
433390SW11	Ciyattville-Nunkin	COLILERT-18	AML	North Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAC Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director