



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

Lovell Engineering Associates
3998 Inner Perimeter Road
Valdosta, GA 31602

PO #: n/a
Client Project #: Lowdes Co. Impaired
Date Sampled: Apr 14, 2020
Apr 15, 2020; Invoice: 434006

Report Summary

Date Received: Apr 14, 2020

FCL Project Manager: William J. Rogers

Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
434006SW1	Staten Road	COLILERT-18	GMR	North Lab	Surface Water
434006SW2	HWY 122 E	COLILERT-18	GMR	North Lab	Surface Water
434006SW3	OLD VALDOSTA RD	COLILERT-18	GMR	North Lab	Surface Water
434006SW4	SHILO RD	COLILERT-18	GMR	North Lab	Surface Water
434006SW5	N VALDOSTA RD	COLILERT-18	GMR	North Lab	Surface Water
434006SW6	WETHERINGTON LANE	COLILERT-18	GMR	North Lab	Surface Water
434006SW7	HWY 84	COLILERT-18	GMR	North Lab	Surface Water
434006SW8	OUSLEY RD	COLILERT-18	GMR	North Lab	Surface Water
434006SW9	CLYATVILLE-NANKIN RD	COLILERT-18	GMR	North Lab	Surface Water
434006SW10	JUMPING GULLEY	COLILERT-18	GMR	North Lab	Surface Water
434006SW11	HICKORY GROVE	COLILERT-18	GMR	North Lab	Surface Water
434006SW12	JOHNSON RD SE	COLILERT-18	GMR	North Lab	Surface Water
434006SW13	B CREEK CYPRESS LAKE	COLILERT-18	GMR	North Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director