



# FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597  
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986  
812 SW Harvey Green Dr, Madison, FL 32340  
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)  
Phone: 772-343-8006 E86562 (South Lab)  
Phone: 850-973-6878 E82405 (North Lab)  
Phone: 305-743-8598 E35834 (Keys Lab)

Lovell Engineering Associates  
3998 Inner Perimeter Road  
Valdosta, GA 31602

PO #: n/a  
Client Project #: Lowndes County Impaired  
Date Sampled: Jun 2, 2020  
Jun 8, 2020; Invoice: 438211

## Report Summary

Date Received: Jun 2, 2020

FCL Project Manager: William J. Rogers

Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
438211SW1	WR2	COLILERT-18	DTB	North Lab	Surface Water
		EPA245.1	AJE	Main Lab	
438211SW2	WR1	COLILERT-18	DTB	North Lab	Surface Water
		EPA245.1	AJE	Main Lab	
438211SW3	FC1	COLILERT-18	DTB	North Lab	Surface Water
438211SW4	FC2	COLILERT-18	DTB	North Lab	Surface Water
438211SW5	WR3	COLILERT-18	DTB	North Lab	Surface Water
		EPA245.1	AJE	Main Lab	
438211SW6	WR4	COLILERT-18	DTB	North Lab	Surface Water
		EPA245.1	AJE	Main Lab	
		EPA6020	EVB	Main Lab	
438211SW7	WR5	COLILERT-18	DTB	North Lab	Surface Water
		EPA245.1	AJE	Main Lab	
		EPA6020	EVB	Main Lab	
438211SW8	WRT1	COLILERT-18	DTB	North Lab	Surface Water
438211SW9	FCO	COLILERT-18	DTB	North Lab	Surface Water
438211SW10	WR6	EPA245.1	AJE	Main Lab	Surface Water
438211SW11	JG2	COLILERT-18	DTB	North Lab	Surface Water
438211SW12	JGI	COLILERT-18	DTB	North Lab	Surface Water
438211SW13	WR7	EPA245.1	AJE	Main Lab	Surface Water

### Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.  
President/Technical Director