



# FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597  
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986  
812 SW Harvey Green Dr, Madison, FL 32340  
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)  
Phone: 772-343-8006 E86562 (South Lab)  
Phone: 850-973-6878 E82405 (North Lab)  
Phone: 305-743-8598 E35834 (Keys Lab)

Lovell Engineering Associates  
3998 Inner Perimeter Road  
Valdosta, GA 31602

PO #: n/a  
Client Project #: LOWNDES COUNTY IMPAIRED  
Date Sampled: Jun 10, 2020  
Jun 11, 2020; Invoice: 439104

## Report Summary

Date Received: Jun 10, 2020

FCL Project Manager: William J. Rogers

Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
439104SW1	WR2	COLILERT-18	GMR	North Lab	Surface Water
439104SW2	WR1	COLILERT-18	GMR	North Lab	Surface Water
439104SW3	FC1	COLILERT-18	GMR	North Lab	Surface Water
439104SW4	FC2	COLILERT-18	GMR	North Lab	Surface Water
439104SW5	WR3	COLILERT-18	GMR	North Lab	Surface Water
439104SW6	WR4	COLILERT-18	GMR	North Lab	Surface Water
439104SW7	WR5	COLILERT-18	GMR	North Lab	Surface Water
439104SW8	WRT1	COLILERT-18	GMR	North Lab	Surface Water
439104SW9	WRT2	COLILERT-18	GMR	North Lab	Surface Water
439104SW10	MC1	COLILERT-18	GMR	North Lab	Surface Water
439104SW11	MC2	COLILERT-18	GMR	North Lab	Surface Water
439104SW12	JG1	COLILERT-18	GMR	North Lab	Surface Water
439104SW13	JG2	COLILERT-18	GMR	North Lab	Surface Water
439104SW14	FC0	COLILERT-18	GMR	North Lab	Surface Water

### Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.  
President/Technical Director