



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

Lovell Engineering Associates
3998 Inner Perimeter Road
Valdosta, GA 31602

PO #: n/a
Client Project #: LOWNDES COUNTY IMPAIRED
Date Sampled: Jun 17, 2020
Jun 19, 2020; Invoice: 439770

Report Summary

Date Received: Jun 17, 2020

FCL Project Manager: William J. Rogers

Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
439770SW1	WR3	COLILERT-18	CWF	North Lab	Surface Water
439770SW2	WR2	COLILERT-18	CWF	North Lab	Surface Water
439770SW3	WR1	COLILERT-18	CWF	North Lab	Surface Water
439770SW4	FC0	COLILERT-18	CWF	North Lab	Surface Water
439770SW5	FC1	COLILERT-18	CWF	North Lab	Surface Water
439770SW6	FC2	COLILERT-18	CWF	North Lab	Surface Water
439770SW7	WR4	COLILERT-18	CWF	North Lab	Surface Water
439770SW8	WR5	COLILERT-18	CWF	North Lab	Surface Water
439770SW9	WRT1	COLILERT-18	CWF	North Lab	Surface Water
439770SW10	WRT2	COLILERT-18	CWF	North Lab	Surface Water
439770SW11	JG2	COLILERT-18	CWF	North Lab	Surface Water
439770SW12	JG1	COLILERT-18	CWF	North Lab	Surface Water
439770SW13	MC1	COLILERT-18	CWF	North Lab	Surface Water
439770SW14	MC2	COLILERT-18	CWF	North Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAP Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director