

Pipeline Construction Progress Photos



Photo 5:
Rock Springs Loop.
View of restored right-of-way around the WCW9C016 wetland crossings on 3/7/2020. Facing east.



Photo 6:
Rock Springs Loop.
View of restored right-of-way around the WCW9C017 wetland crossing on 3/7/2020. Facing east.