

Pipeline Construction Progress Photos



Photo 17:
Station 95.
View of permanently stabilized area around the new addition to the east side of the facility on 3/25/2020. Facing north.



Photo 18:
Station 95.
View of restored temporary workspaces around the scrubbers on 3/25/2020. Facing northwest.