



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

Lovell Engineering Associates
3998 Inner Perimeter Road
Valdosta, GA 31602

PO #: n/a
Client Project #: LCI
Date Sampled: Dec 1, 2021
Dec 13, 2021; Invoice: 491661

Report Summary

Date Received: Dec 1, 2021

FCL Project Manager: William J. Rogers

Laboratory #	Sample Description	Analysis	Chemist	Location	Sample Matrix
491661SW1	WR 2	COLILERT-18 EPA245.1	DTB PCW	North Lab Main Lab	Surface Water
491661SW2	WR 1	COLILERT-18 EPA245.1	DTB PCW	North Lab Main Lab	Surface Water
491661SW3	FC 0	COLILERT-18	DTB	North Lab	Surface Water
491661SW4	FC 1	COLILERT-18	DTB	North Lab	Surface Water
491661SW5	FC 2	COLILERT-18	DTB	North Lab	Surface Water
491661SW6	WR 3	COLILERT-18 EPA245.1	DTB PCW	North Lab Main Lab	Surface Water
491661SW7	WR 4	COLILERT-18 EPA245.1 EPA6020B	DTB PCW EVB	North Lab Main Lab Main Lab	Surface Water
491661SW8	WR 5	COLILERT-18 EPA245.1 EPA6020B	DTB PCW EVB	North Lab Main Lab Main Lab	Surface Water
491661SW9	WR 6	EPA245.1	PCW	Main Lab	Surface Water
491661SW10	WRT 1	COLILERT-18	DTB	North Lab	Surface Water
491661SW11	WRT 2	COLILERT-18	DTB	North Lab	Surface Water

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAC Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director