



**Figure 3.3.10. Gullies Filled with Garbage and Debris Downstream of W. Magnolia St.**