

- Most of the interiors of the Authority's park buildings are clean and show signs of quality maintenance, management, and stewardship. These attributes also help foster a sense of safety and pride in the system's parks. Riley-Ledford Park is a great example of a park building that is clean, well-maintained, and exhibits great management and stewardship.



Clean and well-maintained interior facility at Riley-Ledford Park

- Most of the evaluated park buildings contain equipment that is in good condition, effective, and well-maintained. The Forrest Street Administrative Center, Jaycee Shack Park, Riley-Ledford Park, and the Senior Center are examples of park buildings that contain equipment that is effective and in good working condition.



Appliances and equipment at Jaycee Shack Parks and Forrest Street Administration Center that are in good working condition