



**LEGEND**

- SEWER AND MANHOLES, VITRIFIED CLAY UNLESS OTHERWISE INDICATED
- INSPECTED MANHOLE
- ⊙ MANHOLE PAVED OVER
- ⊖ MANHOLE UNLOCATED
- MANHOLE NOT INSPECTED
- LIFT STATION NO. 5 COLLECTION AREA
- LIFT STATION NO. 6 COLLECTION AREA
- 25 GPM APPROXIMATE INFILTRATION IN GALLONS PER MINUTE

DATE	REVISIONS

LEEDY & CO. NORTH COUNTRY REPORT  
COLLECTION AREA INVESTIGATION STUDY  
QUITMAN, GEORGIA

Scale: 1" = 400'  
 0 100 200 300 400 500 600 700 800 900 1000  
 New SDR 25 12" 1200 ft. installed 12/25/65