

Log of Borehole: B-7

GEO-TECH, INC.

ENGINEERING CONSULTANTS

1016 SE 3rd Avenue
Ocala, Florida
352.694.7711

WWW.GEOTECHFL.COM

Project: PROPOSED SAND MINE, NE 110TH AVENUE, BRONSON, FL

Project No: 22-9204.01.1

Boring Location: (SEE SITE PLAN)

Engineer: NJH/CAH

Client: 3RT PACKING AND SERVICES, LLC

Enclosure: SITE PLAN

| Depth (ft) | Symbol | Description | Consistency | Depth/Elev. | Number | Type | Blows/ft | Standard Penetration Test | | | |
|------------|-----------------|-------------|-------------|-------------|--------|------|----------|---------------------------|--|----|----|
| | | | | | | | | N-Values | | | |
| 33 | | | | | | | | 22 | | | |
| 34 | | | | | | | | MEDIUM DENSE | | 8 | 22 |
| 35 | | | | | | | | MEDIUM DENSE | | 9 | 24 |
| 36 | | | | | | | | | | | |
| 37 | | | | | | | | MEDIUM DENSE | | 10 | 28 |
| 38 | | | | | | | | | | | |
| 39 | | | | | | | | | | | |
| 40 | | | | | | | | MEDIUM DENSE | | 11 | 25 |
| 41 | | | | | | | | | | | |
| 42 | | | | | | | | DENSE | | 12 | 30 |
| 43 | | | | | | | | | | | |
| 44 | | | | | | | | DENSE | | 13 | 30 |
| 45 | | | | | | | | | | | |
| 46 | End of Borehole | 60.0 | | | | | | | | | |
| 47 | | | | | | | | | | | |
| 48 | | | | | | | | | | | |
| 49 | | | | | | | | | | | |
| 50 | | | | | | | | | | | |
| 51 | | | | | | | | | | | |
| 52 | | | | | | | | | | | |
| 53 | | | | | | | | | | | |
| 54 | | | | | | | | | | | |
| 55 | | | | | | | | | | | |
| 56 | | | | | | | | | | | |
| 57 | | | | | | | | | | | |
| 58 | | | | | | | | | | | |
| 59 | | | | | | | | | | | |
| 60 | | | | | | | | | | | |
| 61 | | | | | | | | | | | |
| 62 | | | | | | | | | | | |
| 63 | | | | | | | | | | | |
| 64 | | | | | | | | | | | |

Ground Water Depth: NOT FOUND

Drill Date: JULY 25, 2022

Drilled By: WH/CC/EC

Drill Method: ASTM D-1586

Remarks: (SP) UNIFIED SOIL CLASSIFICATION SYMBOL AS DETERMINED BY VISUAL REVIEW

Soil Profile : 7 OF 23