

Public Waters Pollution Caused Fish Kill Investigation Reporting Form

Photos taken by WRD Fisheries Section personnel during a 9/24/2022 fish kill investigation on One Mile Branch, Valdosta, Georgia. (Lowndes Co.)

Photo 1. Temporary sewer line hookup site (black pipe runs downstream in middle of creekbed)



Photo 2. Unknown fluid (e.g. fuel, hydraulic fluid, etc.) spill located approximately 270m downstream of temporary sewer line hookup and approximately 200m downstream of uppermost dead fish observed.

