

Public Waters Pollution Caused Fish Kill Investigation Reporting Form

Photos taken by WRD Fisheries Section personnel during a 9/24/2022 fish kill investigation on One Mile Branch, Valdosta, Georgia. (Lowndes Co.)

Photo 3. Temporary sewage pipe running along creek bed



Photo 4. Most upstream dead fish observed, located 71m downstream of the Temporary Sewer line hookup (photo 1) and approximately 200m upstream of the potential fluid spill site (photo 2)

