

Public Waters Pollution Caused Fish Kill Investigation Reporting Form

Photos taken by WRD Fisheries Section personnel during a 9/24/2022 fish kill investigation on One Mile Branch, Valdosta, Georgia. (Lowndes Co.)

Photo 5. Location of upstream Temporary sewer line hookup; uppermost dead fish observed; and possible fluid spill site




Photo 6.

