6

8

10

12

13

ANALYTICAL REPORT

PREPARED FOR

Attn: Linda McDonald Madison County Heatlh Department 218 SW Third Avenue Madison, Florida 32340

Generated 11/15/2024 8:52:46 AM

JOB DESCRIPTION

Madison Co HD

JOB NUMBER

674-11067-1

Eurofins Madison 812 S.W. Harvey Greene Drive Madison FL 32340



Eurofins Madison

Job Notes

This report may not be reproduced except in full, and with written approval from the laboratory. The results relate only to the samples tested. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Environment Testing Southeast, LLC Project Manager.

Authorization

Generated 11/15/2024 8:52:46 AM

Authorized for release by Amy Lipscomb, Service Center Manager amy.lipscomb@et.eurofinsus.com (850)973-6878

To	L		_1	0	-1-	1-
ıa	DI	е	O T	しり	nte	nts

Cover Page	1
Table of Contents	3
Definitions/Glossary	4
Case Narrative	5
Detection Summary	6
Client Sample Results	7
QC Association Summary	8
Lab Chronicle	9
Certification Summary	10
Method Summary	11
Sample Summary	12
Chain of Custody	13
Receint Chacklists	14

Definitions/Glossary

Client: Madison County Heatlh Department Job ID: 674-11067-1

Project/Site: Madison Co HD

Glossary

QC

RER

RPD

TEF

TEQ

TNTC

RL

Quality Control

Relative Error Ratio (Radiochemistry)

Toxicity Equivalent Factor (Dioxin)

Too Numerous To Count

Toxicity Equivalent Quotient (Dioxin)

Reporting Limit or Requested Limit (Radiochemistry)

Relative Percent Difference, a measure of the relative difference between two points

Ciossary	
Abbreviation	These commonly used abbreviations may or may not be present in this report.
‡	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive

Eurofins Madison

Case Narrative

Client: Madison County Heatlh Department

Project: Madison Co HD

Job ID: 674-11067-1 Eurofins Madison

Job Narrative 674-11067-1

Analytical test results meet all requirements of the associated regulatory program listed on the Accreditation/Certification Summary Page unless otherwise noted under the individual analysis. Data qualifiers and/or narrative comments are included to explain any exceptions, if applicable.

- Matrix QC may not be reported if insufficient sample is provided or site-specific QC samples were not submitted. In these
 situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD may be performed, unless otherwise
 specified in the method.
- · Surrogate and/or isotope dilution analyte recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in the narrative.

Regulated compliance samples (e.g. SDWA, NPDES) must comply with the associated agency requirements/permits.

Receipt

The samples were received on 11/14/2024 12:13 PM. Unless otherwise noted below, the samples arrived in good condition, and, where required, properly preserved and on ice.

Biology

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Eurofins Madison

Job ID: 674-11067-1

Page 5 of 14 11/15/2024

Detection Summary

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Client Sample ID: BOUNDARY BEND BOAT RAMP Lab Sample ID: 674-11067-1

Analyte	Result	Qualifier	PQL	MDL	Unit	Dil Fac	D	Method	Prep Type
Escherichia coli	108.0		10.0	10.0	MPN/100mL	1	_	9223B	Total/NA
Coliform, Fecal	259.0		10.0	10.0	MPN/100mL	1		Colilert-18	Total/NA

Lab Sample ID: 674-11067-2 **Client Sample ID: SR6**

Analyte	Result	Qualifier	PQL	MDL	Unit	Dil Fac	D	Method	Prep Type
Escherichia coli	158.0		10.0	10.0	MPN/100mL	1	_	9223B	Total/NA
Coliform, Fecal	241.0		10.0	10.0	MPN/100mL	1		Colilert-18	Total/NA

Client Sample ID: CR 150 Lab Sample ID: 674-11067-3

Analyte	Result	Qualifier	PQL	MDL	Unit	Dil Fac	D	Method	Prep Type
Escherichia coli	189.0		10.0	10.0	MPN/100mL	1	_	9223B	Total/NA
Coliform, Fecal	341.0		10.0	10.0	MPN/100mL	1		Colilert-18	Total/NA

Client Sample ID: CR 145 Lab Sample ID: 674-11067-4

Analyte	Result Qualifier	PQL	MDL Unit	Dil Fac	D Method	Prep Type
Escherichia coli	281.0	10.0	10.0 MPN/100mL	1	9223B	Total/NA
Coliform, Fecal	1012.0	10.0	10.0 MPN/100mL	1	Colilert-18	Total/NA

This Detection Summary does not include radiochemical test results.

Job ID: 674-11067-1

Client Sample Results

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Client Sample ID: BOUNDARY BEND BOAT RAMP

Date Collected: 11/14/24 09:50

Date Received: 11/14/24 12:13

Method: SM 9223B - Coliforms, Total, and E.Coll (Colilert - Quanti Tray)

 Analyte
 Result
 Qualifier
 PQL
 MDL Unit
 D Prepared
 Analyzed
 Dil Fac

 Escherichia coli
 10.0
 10.0
 10.0
 MPN/100mL
 11/14/24 13:20
 1

Method: IDEXX Colilert-18 - Fecal Coliforms

Client Sample ID: SR6 Lab Sample ID: 674-11067-2

Date Collected: 11/14/24 10:30

Date Received: 11/14/24 12:13

Method: SM 9223B - Coliforms, Total, and E.Coll (Colilert - Quanti Tray)

Method: IDEXX Colilert-18 - Fecal Coliforms

Analyte Result Qualifier PQL MDL Unit D Prepared Analyzed Dil Fac 10.0 10.0 MPN/100mL 11/14/24 13:20 Coliform, Fecal 241.0

Client Sample ID: CR 150 Lab Sample ID: 674-11067-3

Date Collected: 11/14/24 11:11

Date Received: 11/14/24 12:13

Method: SM 9223B - Coliforms, Total, and E.Coll (Colilert - Quanti Tray)

 Analyte
 Result
 Qualifier
 PQL
 MDL
 Unit
 D
 Prepared
 Analyzed
 Dil Fac

 Escherichia coli
 189.0
 10.0
 10.0
 MPN/100mL
 11/14/24 13:20
 1

Method: IDEXX Colilert-18 - Fecal Coliforms

 Analyte
 Result
 Qualifier
 PQL
 MDL
 Unit
 D
 Prepared
 Analyzed
 Dil Fac

 Coliform, Fecal
 341.0
 10.0
 MPN/100mL
 11/14/24 13:20
 1

Client Sample ID: CR 145

Date Collected: 11/14/24 11:46

Date Received: 11/14/24 12:13

Method: SM 9223B - Coliforms, Total, and E.Coll (Colilert - Quanti Tray)

 Analyte
 Result
 Qualifier
 PQL
 MDL
 Unit
 D
 Prepared
 Analyzed
 Dil Fac

 Escherichia coli
 281.0
 10.0
 MPN/100mL
 11/14/24 13:20
 1

Method: IDEXX Colilert-18 - Fecal Coliforms

Eurofins Madison

11/15/2024

Job ID: 674-11067-1

Matrix: Water

Matrix: Water

Matrix: Water

Matrix: Water

Lab Sample ID: 674-11067-4

Lab Sample ID: 674-11067-1

3

4

6

8

46

11

12

K

•

QC Association Summary

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Job ID: 674-11067-1

Biology

Analysis Batch: 3766

Lab Sample ID	ab Sample ID Client Sample ID		Matrix	Method	Prep Batch
674-11067-1	BOUNDARY BEND BOAT RAMP	Total/NA	Water	Colilert-18	
674-11067-2	SR6	Total/NA	Water	Colilert-18	
674-11067-3	CR 150	Total/NA	Water	Colilert-18	
674-11067-4	CR 145	Total/NA	Water	Colilert-18	

Analysis Batch: 3767

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
674-11067-1	BOUNDARY BEND BOAT RAMP	Total/NA	Water	9223B	
674-11067-2	SR6	Total/NA	Water	9223B	
674-11067-3	CR 150	Total/NA	Water	9223B	
674-11067-4	CR 145	Total/NA	Water	9223B	

A

6

7

_

10

11

12

1:

Lab Chronicle

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Client Sample ID: BOUNDARY BEND BOAT RAMP

Date Collected: 11/14/24 09:50

Lab Sample ID: 674-11067-1

Matrix: Water

Job ID: 674-11067-1

Date Received: 11/14/24 12:13

	Batch	Batch		Dilution	Batch			Prepared
Prep Type	Туре	Method	Run	Factor	Number	Analyst	Lab	or Analyzed
Total/NA	Analysis	9223B		1	3767	SH	EET MAD	11/14/24 13:20
Total/NA	Analysis	Colilert-18		1	3766	SH	EET MAD	11/14/24 13:20

Client Sample ID: SR6

Date Collected: 11/14/24 10:30

Date Received: 11/14/24 12:13

Lab Sample	ID: 674-11067-2
------------	-----------------

Matrix: Water

Batch Dilution Batch Prepared Batch Prep Type Туре Method Run Factor Number Analyst Lab or Analyzed Total/NA 9223B SH EET MAD 11/14/24 13:20 Analysis 3767 Total/NA 11/14/24 13:20 Analysis Colilert-18 1 3766 SH **EET MAD**

Client Sample ID: CR 150 Lab Sample ID: 674-11067-3

Date Collected: 11/14/24 11:11

Date Received: 11/14/24 12:13

Date Received: 11/14/24 12:13

Matrix: Water

	Batch	Batch		Dilution	Batch			Prepared
Prep Type	Туре	Method	Run	Factor	Number	Analyst	Lab	or Analyzed
Total/NA	Analysis	9223B		1	3767	SH	EET MAD	11/14/24 13:20
Total/NA	Analysis	Colilert-18		1	3766	SH	EET MAD	11/14/24 13:20

Client Sample ID: CR 145 Lab Sample ID: 674-11067-4

Date Collected: 11/14/24 11:46 **Matrix: Water**

Batch Batch Dilution Batch Prepared Prep Type Туре Method Run Factor **Number Analyst** Lab or Analyzed Total/NA Analysis 9223B 3767 SH EET MAD 11/14/24 13:20 Total/NA Analysis Colilert-18 1 3766 SH **EET MAD** 11/14/24 13:20

Laboratory References:

EET MAD = Eurofins Madison, 812 S.W. Harvey Greene Drive, Madison, FL 32340, TEL (850)973-6878

Eurofins Madison

Accreditation/Certification Summary

Client: Madison County Heatlh Department Job ID: 674-11067-1

Project/Site: Madison Co HD

Laboratory: Eurofins Madison

The accreditations/certifications listed below are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Florida	NELAP	E82405	06-30-25

ID 074 44007 4

3

6

8

9

11

12

Method Summary

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Job ID: 674-11067-1

Method	Method Description	Protocol	Laboratory
9223B	Coliforms, Total, and E.Coll (Colilert - Quanti Tray)	SM	EET MAD
Colilert-18	Fecal Coliforms	IDEXX	EET MAD

Protocol References:

IDEXX = IDEXX Laboratories

SM = "Standard Methods For The Examination Of Water And Wastewater"

Laboratory References:

EET MAD = Eurofins Madison, 812 S.W. Harvey Greene Drive, Madison, FL 32340, TEL (850)973-6878

2

-0

4

_

0

0

10

11

12

Sample Summary

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Job ID: 674-11067-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
674-11067-1	BOUNDARY BEND BOAT RAMP	Water	11/14/24 09:50	11/14/24 12:13
674-11067-2	SR6	Water	11/14/24 10:30	11/14/24 12:13
674-11067-3	CR 150	Water	11/14/24 11:11	11/14/24 12:13
674-11067-4	CR 145	Water	11/14/24 11:46	11/14/24 12:13

4

5

6


8

9

11

11

12



Login Sample Receipt Checklist

Client: Madison County Heatlh Department Job Number: 674-11067-1

Login Number: 11067 List Source: Eurofins Madison

List Number: 1 Creator: Briggs, Donna

Creator: Briggs, Donna		
Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>True</td> <td></td>	True	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	True	

6

0

9

10

12