13

ANALYTICAL REPORT

PREPARED FOR

Attn: Linda McDonald Madison County Heatlh Department 218 SW Third Avenue Madison, Florida 32340

Generated 11/19/2024 12:43:01 PM

JOB DESCRIPTION

Madison Co HD

JOB NUMBER

674-11083-1

Eurofins Madison 812 S.W. Harvey Greene Drive Madison FL 32340



Eurofins Madison

Job Notes

This report may not be reproduced except in full, and with written approval from the laboratory. The results relate only to the samples tested. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

The test results in this report relate only to the samples as received by the laboratory and will meet all requirements of the methodology, with any exceptions noted. This report shall not be reproduced except in full, without the express written approval of the laboratory. All questions should be directed to the Eurofins Environment Testing Southeast, LLC Project Manager.

Authorization

Generated 11/19/2024 12:43:01 PM

Authorized for release by Amy Lipscomb, Service Center Manager amy.lipscomb@et.eurofinsus.com (850)973-6878

Eurofins Madison is a laboratory within Eurofins Environment Testing Southeast, LLC, a company within Eurofins Environment Testing Group of Companies
Page 2 of 14
11/19/2024

2

3

4

9

10

4.0

Table of Contents				
Cover Page	1			
Table of Contents	3			
Definitions/Glossary	4			
Case Narrative	5			
Detection Summary	6			
Client Sample Results	7			
QC Association Summary	8			
Lab Chronicle	9			
Certification Summary	10			
Method Summary	11			
Sample Summary	12			
Chain of Custody	13			
Receint Checklists	14			

3

4

6

8

10

11

Definitions/Glossary

Client: Madison County Heatlh Department Job ID: 674-11083-1

Project/Site: Madison Co HD

Glossary

QC RER

RL

RPD

TEF

TEQ

TNTC

Quality Control

Relative Error Ratio (Radiochemistry)

Toxicity Equivalent Factor (Dioxin)

Too Numerous To Count

Toxicity Equivalent Quotient (Dioxin)

Reporting Limit or Requested Limit (Radiochemistry)

Relative Percent Difference, a measure of the relative difference between two points

Cioodary	
Abbreviation	These commonly used abbreviations may or may not be present in this report.
☼	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive

Eurofins Madison

G

4

7

10

46

1.

Case Narrative

Client: Madison County Heatlh Department

Project: Madison Co HD

Job ID: 674-11083-1 Eurofins Madison

Job Narrative 674-11083-1

Analytical test results meet all requirements of the associated regulatory program listed on the Accreditation/Certification Summary Page unless otherwise noted under the individual analysis. Data qualifiers and/or narrative comments are included to explain any exceptions, if applicable.

- Matrix QC may not be reported if insufficient sample is provided or site-specific QC samples were not submitted. In these
 situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD may be performed, unless otherwise
 specified in the method.
- · Surrogate and/or isotope dilution analyte recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in the narrative.

Regulated compliance samples (e.g. SDWA, NPDES) must comply with the associated agency requirements/permits.

Receipt

The sample was received on 11/18/2024 11:53 AM. Unless otherwise noted below, the sample arrived in good condition, and, where required, properly preserved and on ice.

Biology

No additional analytical or quality issues were noted, other than those described above or in the Definitions/ Glossary page.

Eurofins Madison

Job ID: 674-11083-1

Page 5 of 14 11/19/2024

Detection Summary

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Client Sample ID: CR 145

Job ID: 674-11083-1

Lab Sample ID: 674-11083-1

Analyte	Result Qualifier	PQL	MDL Unit	Dil Fac	Method	Prep Type
Escherichia coli	30.0	10.0	10.0 MPN/100mL	1	9223B	Total/NA
Coliform, Fecal	262.0	10.0	10.0 MPN/100mL	1	Colilert-18	Total/NA

9

Δ

4

6

Q

9

10

10

1:

Client Sample Results

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Client Sample ID: CR 145 Lab Sample ID: 674-11083-1

Date Collected: 11/18/24 11:25 Matrix: Water

Date Received: 11/18/24 11:53

	Method: SM 9223B - Coliforms, Tot	al, and E.Coll (Colilert - C	Quanti Tray)						
	Analyte	Result Qualifier	PQL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Escherichia coli		30.0 10.		10.0	MPN/100mL			11/18/24 14:50	1
	Method: IDEXX Colilert-18 - Fecal C	Coliforms							

П	Mathadi	IDEVV Ca	1:1aut 40 F	and Californ	
	wetnoa:	IDEXX CO	mert-16 - F	ecal Coliforn	IS

Analyte	Result Qualifier	PQL	MDL Unit	D	Prepared	Analyzed	Dil Fac
Coliform, Fecal	262.0	10.0	10.0 MPN/100mL			11/18/24 14:50	1

Job ID: 674-11083-1

QC Association Summary

Client: Madison County Heatlh Department

Job ID: 674-11083-1 Project/Site: Madison Co HD

Biology

Analysis Batch: 3775

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
674-11083-1	CR 145	Total/NA	Water	Colilert-18	

Analysis Batch: 3777

Lab Sample I	D Client Sample ID	Prep Type	Matrix	Method	Prep Batch
674-11083-1	CR 145	Total/NA	Water	9223B	

Lab Chronicle

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Client Sample ID: CR 145

Lab Sample ID: 674-11083-1

Matrix: Water

Job ID: 674-11083-1

Date Collected: 11/18/24 11:25 Date Received: 11/18/24 11:53

	Batch	Batch		Dilution	Batch			Prepared
Prep Type	Type	Method	Run	Factor	Number	Analyst	Lab	or Analyzed
Total/NA	Analysis	9223B		1	3777	DB	EET MAD	11/18/24 14:50
Total/NA	Analysis	Colilert-18		1	3775	DB	EET MAD	11/18/24 14:50

Laboratory References:

EET MAD = Eurofins Madison, 812 S.W. Harvey Greene Drive, Madison, FL 32340, TEL (850)973-6878

-

3

9

10

15

1:

Accreditation/Certification Summary

Client: Madison County Heatlh Department Job ID: 674-11083-1

Project/Site: Madison Co HD

Laboratory: Eurofins Madison

The accreditations/certifications listed below are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Florida	NELAP	E82405	06-30-25

.

3

4

8

9

11

12

Method Summary

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Job ID: 674-11083-1

Method	Method Description	Protocol	Laboratory
9223B	Coliforms, Total, and E.Coll (Colilert - Quanti Tray)	SM	EET MAD
Colilert-18	Fecal Coliforms	IDEXX	EET MAD

Protocol References:

IDEXX = IDEXX Laboratories

SM = "Standard Methods For The Examination Of Water And Wastewater"

Laboratory References:

EET MAD = Eurofins Madison, 812 S.W. Harvey Greene Drive, Madison, FL 32340, TEL (850)973-6878

a

3

4

5

8

. .

Sample Summary

Client: Madison County Heatlh Department

Project/Site: Madison Co HD

Job ID: 674-11083-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
674-11083-1	CR 145	Water	11/18/24 11:25	11/18/24 11:53

9

4

5

_

9

11

ш

Chain of Custody Record

812 SW Harvey Greene Dr

Madison, FI 32340

Eurofins Madison

Login Sample Receipt Checklist

Client: Madison County Heatlh Department Job Number: 674-11083-1

Login Number: 11083 List Source: Eurofins Madison

List Number: 1

Creator: Briggs, Donna		
Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>True</td> <td></td>	True	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	True	
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	True	

2

4

J

9

10

12