

UTILITIES DEPARTMENT

PH: 229-259-3592

FAX: 229-241-8285

Emergency: 229-434-4132

Director of Utilities

[Jason Barnes](#)



SPILL REPORT TO EPD

TIME/DATE OF MINOR SPILL: Start:11/26/2024(1200)- End11/27/2024 (1300)

REPORT SUBMITTED: 12/2/2024

LOCATION OF SPILL: 2426 Meadowbrook Drive 30.864354736215617, -83.31398074906407

CAUSE OF SPILL: Unknown: debris or possible collapse

ESTIMATED VOLUME DISCHARGED: 1000-2000 Gallons

RECEIVING WATERS: Withlacoochee River (SSO enters Two Mile Branch which merges with Sugar Creek and then Withlacoochee River).

SERVICE BASIN AFFECTED: Suwanee River Basin

WWTP SERVICE AREA NPDES PERMIT: GA0033235

CORRECTIVE ACTION TAKEN TO MITIGATE OR TO REDUCE ADVERSE EFFECTS: Bypass pumps put into place until blockage could be cleared or line repaired. Area sanitized.

SPILL STATUS: Stopped

SIGNS POSTED: Yes

CORRECTIVE ACTION TAKEN TO PREVENT FUTURE SPILL: Line will be monitored by camera for any other potential obstructions and debris. System part of ongoing infrastructure upgrades and repair.

DATE STREAM MONITORING INITIATED: N/A

DATE MEDIA / HEALTH DEPARTMENT / OTHERS NOTIFIED: 12/2/2024

REPORT SUBMITTED BY: Joseph Gangler