



County	<u>Berrien</u>	Picture	<u>3</u> of <u>6</u>	Site Name	<u>GA0033553</u>
Date	<u>10/28/2016</u>	Weather	<u>Sunny</u>	Direction Facing	<u>North</u>
Program	<u>Water Quality</u>	Specialist	<u>Linda Stevens</u>	Time	<u>10:08</u>
Explanation	<u>Picture of portable throw ring located on the effluent catwalk.</u>				



County	<u>Berrien</u>	Picture	<u>4</u> of <u>6</u>	Site Name	<u>GA0033553</u>
Date	<u>10/28/2016</u>	Weather	<u>Sunny</u>	Direction Facing	<u>East</u>
Program	<u>Water Quality</u>	Specialist	<u>Linda Stevens</u>	Time	<u>10:10</u>
Explanation	<u>Picture of vegetation that had been removed located on the far side of the pond dam.</u>				