

## Pipeline Construction Progress Photos



**Photo 1:**  
Rock Springs Loop.  
Overview of restored right-of-way around the SCW9C001 stream crossing on 3/7/2020. Facing west.



**Photo 2:**  
Rock Springs Loop.  
View of restored right-of-way around the WCW9C003 wetland crossing on 3/7/2020. Facing east.