

Pipeline Construction Progress Photos




Photo 3:
Rock Springs Loop.
View of restored right-of-way back from the West Butler Road crossing on 3/7/2020. Facing west.



Photo 4:
Rock Springs Loop.
Overview of restored right-of-way near the WCW9C015 wetland and slide area on 3/7/2020. Facing southwest.