

Pipeline Construction Progress Photos



Photo 15:
Station 95.
View of
restored
temporary
workspace
north of the
facility
entrance road
on 3/25/2020.
Facing west.



Photo 16:
Station 95.
View of the
new addition
on the east
side of the
facility on
3/25/2020.
Facing south.