



FLOWERS CHEMICAL LABORATORIES INC.

P.O. Box 150597, Altamonte Springs, FL 32715-0597
571 NW Mercantile Pl, Suite 111, Port St. Lucie, FL 34986
812 SW Harvey Green Dr, Madison, FL 32340
3980 Overseas Hwy, Suite 103, Marathon, FL 33050

Phone: 407-339-5984 E83018 (Main Lab)
Phone: 772-343-8006 E86562 (South Lab)
Phone: 850-973-6878 E82405 (North Lab)
Phone: 305-743-8598 E35834 (Keys Lab)

Lovell Engineering Associates
3998 Inner Perimeter Road
Valdosta, GA 31602

PO #: n/a
Client Project #: LCI
Date Sampled: Sep 22, 2021
Sep 23, 2021; Invoice: 484137

Report Summary

Date Received: Sep 22, 2021

FCL Project Manager: William J. Rogers

| Laboratory # | Sample Description | Analysis | Chemist | Location | Sample Matrix |
|--------------|--------------------|-------------|---------|-----------|---------------|
| 484137SW1 | WR 2 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW2 | WR 1 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW3 | FC 0 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW4 | FC1 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW5 | FC2 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW6 | WR 3 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW7 | WR 4 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW8 | WR 5 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW9 | WRT 1 | COLILERT-18 | DTB | North Lab | Surface Water |
| 484137SW10 | WRT 2 | COLILERT-18 | DTB | North Lab | Surface Water |

Certificate of Results

Sample integrity was certified prior to analysis. Test results meet all requirements of the NELAC Standards except as noted in the Quality Control Report. Uncertainties for these data are available on request. This report may not be reproduced in part; results relate only to items tested.



Jefferson S. Flowers, Ph.D.
President/Technical Director