

Buildings/Architecture

STRENGTHS


- Most of the evaluated park buildings have an attractive and aesthetically pleasing appearance, utilizing materials that positively contribute to the context of the park and neighborhood setting. A notable example is the building in Riley-Ledford Park.
- Most park buildings have well-organized and efficient interior layouts with functioning dimensions. Additionally, entries and building orientations are clearly defined and facilitate intuitive access and circulation. Notable examples include Forrest Street Administration Center, Jaycee Shack Park, and Riley-Ledford Park.
- Most park buildings contain interior finishes, furnishings, equipment, and systems that appear to be well-maintained and in good working condition. Notable examples include Forrest Street Administration Center, Jaycee Shack Park, Mildred Hunter Community Center, and Riley-Ledford Park.
- Most park buildings contain structural and enclosure elements that appear to be in good condition.



Riley-Ledford Park’s attractive architectural character and scale contributes to the overall appearance and positive first impression of the park and surrounding area



Well-organized and efficient interior layouts with functioning dimensions at Forrest Street Administration Center and Jaycee Shack Park



Interior finishes, furniture, and equipment in Jaycee Shack Park and Mildred Hunter Community Center that are in good condition